


For Instructions, please see:

<http://www.erni.com/DB/derating/DERATING-Instructions.pdf>

DERATING CURVE (Current carrying capacity acc. IEC 60512-5-2 Test 5b)
Microspeed connector with 50 contacts




	0	10	20	30	40	50	60	70	80	90
Base curve [A]			1,08	1,00	0,91	0,79	0,67	0,50	0,25	
Derating curve [A]			0,86	0,80	0,73	0,63	0,53	0,40	0,20	

For Instructions, please see:

<http://www.erni.com/DB/derating/DERATING-Instructions.pdf>

DERATING CURVE (Current carrying capacity acc. IEC 60512-5-2 Test 5b)
Microspeed connector with 50 contacts



	0	10	20	30	40	50	60	70	80	90	100	110	120	130
Base curve [A]			1,35	1,30	1,23	1,16	1,08	1,00	0,91	0,79	0,67	0,50	0,25	
Derating curve [A]			1,08	1,04	0,99	0,93	0,86	0,80	0,73	0,63	0,53	0,40	0,20	