


For Instructions, please see:

<http://www.erni.com/DB/derating/DERATING-Instructions.pdf>



DERATING CURVE (Current carrying capacity acc. IEC 60512-5-2 Test 5b)
Power Tap connector (SVA) with formed thread 6 contacts (pressfit termination)



Base curve [A]			49,5	46	43	39	35	30,5	25	19	10	
Derating curve [A]			39,60	36,80	34,40	31,20	28,00	24,40	20,00	15,20	8,00	