


For Instructions, please see:

<http://www.erni.com/DB/derating/DERATING-Instructions.pdf>

DERATING CURVE (Current carrying capacity acc. IEC 60512-5-2 Test 5b)
D-Sub connector TMC 90° and 180° Ba 8 with 25 contacts
(Pressfit, SMT and THR termination)



Base curve [A]														
	0	10	20	30	40	50	60	70	80	90	100	110	120	130
Derating curve [A]			4,48	4,32	4,08	3,84	3,6	3,32	2,96	2,6	2,16	1,6	0,8	